Maryland Historical Trust

Maryland Inventory of Historic Properties number: F-1-82
Name: 10015/MD28 over for of Potomac Ruce
The bridge referenced herein was inventoried by the Maryland State Highway Administration as part of the Historic Bridge Inventory, and SHA provided the Trust with eligibility determinations in February 2001. The Trust accepted the Historic Bridge Inventory on April 3, 2001. The bridge received the following determination of eligibility.
Eligibility Recommended X MARYLAND HISTORICAL TRUST Eligibility Not Recommended
Criteria: A B C D Considerations: A B C D E F G None Comments:
Reviewer, OPS: _Anne E. Bruder Date:3 April 2001 Reviewer, NR Program:Peter E. Kurtze Date:3 April 2001

MARYLAND INVENTORY OF HISTORIC BRIDGES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION/MARYLAND HISTORICAL TRUST

MHT No. F-1-82

SHA Bridge No. 10015 Bridge name MD 28 over Branch of Potomac River
LOCATION: Street/Road name and number [facility carried] MD 28
City/town Point of Rocks Vicinity X
County Frederick
This bridge projects over: Road Railway Water X Land
Ownership: State X County Municipal Other
HISTORIC STATUS: Is the bridge located within a designated historic district? Yes No X National Register-listed district National Register-determined-eligible district Locally-designated district Other
Name of district
BRIDGE TYPE: Timber Bridge: Beam Bridge Truss -Covered Trestle Timber-And-Concrete
Stone Arch Bridge
Metal Truss Bridge
Movable Bridge: Swing Bascule Single Leaf Bascule Multiple Leaf Vertical Lift Retractile Pontoon
Metal Girder: Rolled Girder: Plate Girder: Rolled Girder Concrete Encased: Plate Girder:
Metal Suspension
Metal Arch
Metal Cantilever
Concrete X : Concrete Arch Concrete Slab X Concrete Beam Rigid Frame Other Type Name

			10000000000000000000000000000000000000	
n	ESCI) ID	TIO	N.
v	LOUI	\11	\mathbf{I}	

Setting: Urban _____ Small town X Rural _____

Describe Setting: Bridge No. 10015 carries MD 28 over a branch of the Potomac River. It is near of Point of Rocks in southern Frederick County. It is a rural area with farms and wooded sections. The stream flows from north to south.

Describe Superstructure and Substructure:

Bridge 10015 is a single span concrete slab bridge. The bridge has a span length of 20', a total length of 21' and a clear roadway width of 27'. The structure was built in 1937 and conforms to 1930 standard concrete slab bridge plans. The parapets are open and have decorative features including panelling and end blocks. The bridge has six inches of additional wearing surface.

A 1993 State inspection report found that that the abutments had surface erosion or scaling at the waterline, some spalling and efflorescence. Wingwalls also exhibited some deterioration.

The concrete slab has shifted to the south 1- 1/2" causing gaps at the wingwalls and cracks. The interface between the concrete slab and wingwall at the southwest wingwall was tight. The southeast wingwall top section had fractured due to the force exerted on the concrete by the slab movement. The abutment is cracked. The underside of the concrete slab has a few spalled areas with exposed reinforcement.

Discuss Major Alterations:

There have been no major alterations to this bridge.

HISTORY:

WHEN was the bridge built 1937

This date is: Actual X Estimated ______

Source of date: Plaque _____ Design plans _____ County bridge files/inspection form _____

Other (specify): SHA files

WHY was the bridge built?

The need for a more efficient transportation network and increased load capacity in the decades following World War I.

WHO was the designer?

State Highway Administration

WHO was the builder?

State Highway Administration

WHY was the bridge altered?

This bridge has not been altered.

Was this bridge built as part of an organized bridge-building campaign?

As part of an effort by the State to increase load capacity on secondary roads during the 1930s.

SURVEYOR/HISTORIAN ANALYSIS:

This bridge may have National	Register significance for its association with:
A - Events	B- Person
C- Engineering/architec	ctural character

Was the bridge constructed in response to significant events in Maryland or local history?

Reinforced concrete slab bridges are a twentieth century structure type, easily adapted to the need for expedient engineering solutions. Reinforced concrete technology developed rapidly in the early twentieth century with early recognition of the potential for standardized design. The first U.S. attempt to standardize concrete design specifications came in 1903-04 with the formation of the Joint Committee on Concrete and Reinforced Concrete of the American Society of Civil Engineers.

Maryland's road and bridge improvement programs mirrored economic cycles. The first road improvement program of the State Roads Commission was a 7 year program, starting with the Commission's establishment in 1908 and ending in 1915. Due to World War I, the period from 1916 -1920 was one of relative inactivity; only roads of first priority were built. Truck traffic resulting from war-related factories and military installations generated new, heavy traffic unanticipated by the builders of the early road system. From 1920 to 1929, numerous highway improvements occurred in response to the increase in Maryland motor vehicles from 103,000 in 1920 to 320,000 in 1929, with emphasis on the secondary system of feeder roads which moved traffic from the primary roads built before World War I. After World War I, Maryland's bridge system also was appraised as too narrow and structurally inadequate for the increasing traffic, with plans for an expanded bridge program to be handled by the Bridge Division, set up in 1920. In 1920 under Chapter 508 of the Acts of 1920 the State issued a bond of \$3,000,000.00 for road construction; the primary purpose of these monies was to meet the state obligations involving the construction of rural post roads. The secondary purpose of these monies was to fund [with an equal sum from the counties] the building of lateral roads. The number of hard surfaced roads on the state system grew from 2000 in 1920 to 3200 in 1930. By 1930, Maryland's primary system had become inadequate to the huge freight trucks and volume of passenger cars in use, with major improvements occurring in the late 1930s. Most improvements to local roads waited until the years after World War II.

With a diverse topographical domain encompassing numerous small and large crossings, Maryland engineers quickly recognized the need for expedient design and construction.

In the early years, there was a need to replace the numerous single lane timber bridges. Walter Wilson Crosby, Chief Engineer stated in 1906, "The general plan has been to replace these [wood bridges] with pipe culverts or concrete bridges and thus forever do way with the further expense of the maintenance of expensive and dangerous wooden structures". Within a few years, readily constructed standardized bridges of concrete were being built throughout the state.

The creation of standard plans and a description of their use was first announced in the 1912-15 Reports of the State Roads Commission whereby bridges spanning up to 36 feet were to use standardized designs.

Published on a single sheet, the 1912 Standard Plans included those structures that were amenable to such an approach: slab spans, (deck) girder spans, box culverts, box bridges, abutments, and piers (State Roads Commission 1912). Slab spans, with lengths of 6 to 16 feet in two foot increments, featured a solid parapet that was integrated into the slab, with a roadway of 22 feet.

In the Report for the years 1916-1919, a revision of the standard plans was noted:

During the four years covered by this report, it has been found necessary to revise our standard plans for culverts and bridges, to take care of the increased tonnage which they have been forced to carry. Army cantonments...increased their operations several hundred per cent, and the brunt of the enormous truck traffic resulting therefrom, was borne by the State Roads of Maryland. In addition to these war activities, freight motor lines from Baltimore to Washington, Philadelphia, New York, and various points throughout Maryland, and the weight of many of these trucks when loaded, was in excess of the loads for which our early bridges were designed (State Roads Commission 1920:56).

Published on separate sheets, the new standard plans (State Roads Commission 1919) for slab bridges reveal that the major changes was an increase in roadway width from 22 feet to 24 feet and a redesign of the reinforcement. The slab spans continued to feature solid parapets integrated into the span. The range of span lengths remained 6 to 16 feet, but the next year (1920) witnessed the issue of a supplemental plan for a 20 foot long slab span (State Roads Commission 1920).

The 1924 standard plans remained in effect until 1930, when the roadway width for all standard plan bridges was increased to 27 feet in order to accommodate the increasing demands of automobile and truck traffic (State Roads Commission 1930). The range of span lengths remained the same, but there were some changes designed to increase load bearing capacities. The reinforcing bars were increased in thickness. Visually, the 1930 design can be distinguished from its predecessors by the pierced concrete railing that was introduced at this time.

Three years later, in 1933, a new set of standard plans was introduced (State Roads Commission 1933). This time, their preparation was not announced in the Report; new standard plans were by this time nothing special - they had indeed become standard. Once again accommodating the ever-increasing demands of traffic, the roadway width was increased, this time to 30 feet. The slab span's reinforcing bars remained the same diameter but were placed closer together to achieve still more load bearing capacity.

A system of standard nomenclature for plans was introduced at this time: span type was indicated by a two-letter designator followed by span length and the year of the plan. Thus, CS-18-33 indicates an 18 foot concrete slab of the 1933 standard plan design; CG-36-33 was a 36 foot concrete girder (T-beam) of the same year. The inclusion of the year designator gave ready access to design details for each bridge and indicates that the State Roads Commission anticipated revisions to standard plans.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

There is no evidence that the construction of this bridge had a significant impact on the growth and development of this area. The area around the bridge is largely undeveloped.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from the historic/visual character of the potential district?

The bridge is not located in an area which may be eligible for historic designation.

Is the bridge a significant example of its type?

No, this bridge is an undistinguished example of a standardized concrete bridge.

Does the bridge retain integrity of important elements described in Context Addendum? Yes, the character defining elements have retained their integrity.

Is the bridge a significant example of the work of a manufacturer, designer, and/or engineer? No, this is an undistinguished, standardized bridge conforming to standardized state plans.

Should the bridge be given further study before an evaluation of its significance is made? No further evaluation is necessary to determine National Register significance.

BIBLIOGRAPHY:

County inspection/bridge files Other (list):

SHA inspection/bridge files X

SURVEYOR:

Date bridge recorded 8/95


Name of surveyor Leo Hirrell

Organization/Address P.A.C. Spero & Compnay, 40 W. Chesapeake Avenue, Suite 412, Baltimore,

Maryland 21204

Phone number 410-296-1635

FAX number 410-296-1670





Inventory # F-1-82

Name 10015- M	DZB OVER	A BLA	NCH INTO	POTOMAC	RIVER
County/State	FRE DER	uck	COUNT	Y/MD	

Date 195

Description ELEVATION LOOKING SOUTH

Location of Negative SHA



Inventory # F-1-82

Name 10015 MO28 0	WER A BRANCH INTO POTUMAC PC
County/State FRED	ERICK COUNTY IMO
	FRANK JULIANO

Location of Negative ___ SHA Description ELEVATION LOOKING NORTH



Name 10015-MD 28 OVER A BRANCH INTO PITUMAC RIVER County/State FREDERICK COUNTY/MD Name of Photographer FRANK JULIANO Date 195

Location of Negative SHA

Description APPROACH WEST

Jumber 25 of 36 3



Inventory # *F-1-82*

Name 10015- MD 28 OVER A BRANCH INTO POTOMAC PLIVER
County/State FREDERICK COUNTY/MD
Name of Photographer FRANK JULIANO
Date 195

Location of Negative SHA

Description APPROACH EAST

Number 20 of 36 4